



An aerial night photograph of a large industrial facility, likely a power plant or refinery. The image shows a massive, curved, metallic roof structure in the foreground, illuminated by bright orange and yellow lights. In the background, various industrial buildings and structures are visible, some with red emergency lights. The sky is dark with some clouds, and a thin line of light on the horizon suggests a sunset or sunrise.

**Коригування роботи рятувальників при  
ліквідації наслідків влучання ворожого БпЛА  
в об'єкт «Укриття-2»**

# Основні характеристики Нового Безпечного Укриття (НБУ) "Укриття-2"





**14 лютого 2025 року 02:08 ДСП ЧАЕС внаслідок влучання БпЛА (Герань-2) у комплекс “Укриття-2”, виникло загорання мембрани на висоті 87 м між металевим покриттям та утеплювачем. Відбулося розповсюдження тління мембрани під металевим покриттям.**


# Основна роль БПЛА з тепловізійною камерою під час ліквідації НС

- Проведення розвідки та моніторинг розвитку пожежі




# Основна роль БПЛА з тепловізійною камерою під час ліквідації НС

- Виявлення осередків тління




# Основна роль БПЛА з тепловізійною камерою під час ліквідації НС




# Основна роль БПЛА з тепловізійною камерою під час ліквідації НС

- Коригування рятувальників



# Основна роль БПЛА з тепловізійною камерою під час ліквідації НС



# Основна роль БПЛА з тепловізійною камерою під час ліквідації НС

- Збір даних для подальших аналізів та оцінки пошкоджень



# Основна роль БПЛА з тепловізійною камерою під час ліквідації НС



